Duplicate / Triplicate

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0047, W0024, W0043, W0012, W0039	NA	eagle bekary
Segment No.	**Total Length (m)**	
15/C-W0047/S114923	220.74	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	95.04	77.511011	13.047711	77.510695	13.046909	eagle bekary road	dead end
2	125.70	77.510451	13.047920	77.510049	13.046854	eagle bekary road	5th cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of cc drain & cc road kempegowda nagara 6th A cross & 6th B cross roads in dasarahalli ward no 15	3000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	cc road & cc drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		015-000010
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/467/2019-20	13/12/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
07/03/2020	06/03/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Sri Hanumantharaju B T		3033304.00
Phone No.	**E-Mail ID**	
9742107961		

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0047, W0024, W0043, W0012,

Scanned by CamScanner

Inspection Details

Number of Trees	Any Other Information	Name
	cc road & drain	archana
Date of Inspection	**Remarks**	
05/03/2021	completed	

Category	Image	Photo Remark
Drain Condition		
Footpath Condition		
Road Condition		
Segment End		
Segment Start		

Remarks

Designation	Approver Name	Date	Target Date	Remark

e: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0047, W0024, W0043, W0012,

Scanned by CamScanner